CCR No. *SF-98-0065* Logged Date *1/20/98*	Rev. -	Request Type CCR	
Priority Routine [X] Urgent [ ] Emergency [ ]	Affected Release V2.0	Change Class II	

Title (description) Add EMASS AMU Network Connection to VATC

Documents Affected	Source Nos (RID, NCR, Action Item, GSFC CCR, etc.) or Tech Reference
921-TDV-002 and 921-TDV-003	CCR 97-1144

RTM Change [ ]   **Start New Baseline** [ ]

Problem
1. CCR 97-1144 added the EMASS AMU to the VATC.
2. Ingest Server host name t1icg01 is incorrecly shown as t1icg03 on the VATC Hardware/Network Diagram.

Proposed Solution
1. Add the EMASS AMU to the VATC network documention.
2. Change Ingest Server host name from t1icg03 to t1icg01 on the VATC Hardware/Network Diagram.

need by 1/21/98

Impact Analysis:

Organizations Affected:

	BOO [ ]	Contracts [ ]	ECS Chief Eng [ ]	FOS [ ]	M&O [ ]
Procurement [ ]	QO [ ]	Rel. Dev [ ]	Rel. A [ ]	Rel. C [ ]	SCDO Arch. [ ]
Science Off [ ]	Security [ ]	Subcontrct [ ]	Sys. Eng [x]	Sys Verf [ ] Acpt	

Cost:	None [x]	Small [ ] (Not exceeding $100,000)	Medium [ ] ($100,000 to $500,000)	Large [ ] (Over $500,000)

Schedule:	None [x]	Other

Additional LOC _____   Man-Months _____

Materials

Originator R. Haynes, Net Eng.	Randy Haynes *Randy Haynes*	*1/20/98*
	Signature	Date
Office HW/Net Eng. Office Manager	Randy Miller/Ezra Jalleta	*1/20/98*
	Signature	Date

Disposition   Approved [X]   Approved w/Comment [ ]   Forward [ ]   Disapproved [ ]

Comments:

CCB Chairperson   Signature   *1/21/98*   Date

ORIGINAL   *ct/cm*